


400 JAMB
5500XT 7"

600 VERT.
5500XT 7"

601 EXP. VERT.
5500XT 7"

401 JAMB
5500XT 7"



100 HEAD
5500XT 7"

NOTE:
MAXIMUM REACTION FOR
55000 SCREW SPLINE SYSTEM IS
1800# @ INTERMEDIATE, 800 # @
JAMBS. FOR HIGHER LOADS USE
MULLION "T" AND "M" ANCHORS
WITH DROP ON HEADS AND SILLS.

500 HORZ.
5500XT 7"

NOTE:
MAXIMUM REACTION FOR
55000 SCREW SPLINE SYSTEM IS
1800# @ INTERMEDIATE, 800 # @
JAMBS. FOR HIGHER LOADS USE
MULLION "T" AND "M" ANCHORS
WITH DROP ON HEADS AND SILLS.

200 SILL
5500XT 7"